

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

1508
NE
> 1
1.891 mi.
9984 ft.

CON ED MANHOLE
AVENUE V & OCEAN AVENUE
BROOKLYN, NY

NY Spills S106012416
N/A

Relative:
Higher

Actual:
14 ft.

SPILLS:

Name: CON ED MANHOLE
Address: AVENUE V & OCEAN AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0212539 / 2003-05-05
Facility ID: 0212539
Facility Type: ER
DER Facility ID: 217320
Site ID: 266803
DEC Region: 2
Spill Cause: Unknown
Spill Class: D4
SWIS: 2401
Spill Date: 2003-03-19
Investigator: KMFOLEY
Referred To: Not reported
Reported to Dept: 2003-03-20
CID: 266
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2003-03-20
Spill Record Last Update: 2004-10-14
Spiller Name: Not reported
Spiller Company: CON EDISON
Spiller Address: 4 IRVING PLACE
Spiller Company: 001
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was FOLEY Con Ed e2mis #147594: 3/19/03 12:30 HRS. M. ADAMO #28458 OF BKLYN/QUEENS EQUIPMENT GROUP REPORTS AT 12:15 HRS. FOUND AN UNDIAPERABLE SHEEN OF UNKNOWN OIL ON APPROX. 500 GAL. WATER. SOURCE UNKNOWN -- TRANSFORMER WAS REMOVED FROM STRUCTURE THIS MORNING AND WAS NOT LEAKING. ENV. STOP TAG #39257 PLACED. LIQUID SAMPLE TAKEN ON E PRIORITY TURNAROUND. CHAIN OF CUSTODY FORM # CC-05031. CLEANUP PENDING PCB RESULTS FROM CHEM LAB. 3/19/03 15:20 HRS - SEDA EDIP OS EQUIP GRP - REPORTS COURIER PICKED UP SAMPLE @ 1515 HRS. UPDATE - 19-MAR-2003 21:18 HRS.. LSN# 03-02285 , SAMPLE TYPE: OIL, AROCLOR: 1260, RESULT: < 1 PPM. UPDATE - 20-MAR-2003 01:37 HRS. VEHICLE BLOCKING ACCESS TO STRUCTURE. UPDATE: 3/26/03 - 1300 G. KERN - ENV. OPS., REPORTS CLEANUP COMPLETED BY DOUBLE WASHING STRUCTURE WITH BULLDOG. WASTE PRODUCT REMOVED WITH VACTOR. SUMP FOUND SEALED. TAG # 39257 REMOVED. TJ - 50495"
Remarks: "MANHOLE TM1276. SHEEN ON 500 GALLONS OF WATER. TRANSFORMER HAS BEEN REMOVED. NO SIGN OF LEAKS. SAMPLES WERE TAKEN. TEST RESULTS INDICATE LESS THAN 1 PPM'S OF PCB'S. CLEAN UP PENDING REMOVAL OF A CAR THAT'S PARKED OVER THE MANHOLE. CON EDISON REFERENCE NUMBER 147594."

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

All Materials:

Site ID:	266803
Operable Unit ID:	865994
Operable Unit:	01
Material ID:	512272
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported